

F19. 3







FIG. SA




F14.5

		607 604			600	i de la companya de l
	/		606	608	600	612 614
					//600/	
Maestro C	entral	- [Log Window]		•	,	
The View	Log	Mydow Help	/	7	/	# 6 X
al×1/%		/		7		
						<u> </u>
erver Name		Date/Time /	Source	Category	Description	Deteit -
baba	1	11:29:16 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	2	11:29:17 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	3	11:34:38 AM Thu. September 4, 1997	Slot Fan Aleit	serious	The speed of the I/O slot fan i	Please ch
baba	4	11:34:39 AM Thu September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	5	11:36:36 AM Thu. September 4, 1997	Slot Fan Aleit	serious	The speed of the I/O slot fan i	Please ch
a baba	6 7	11:36:38 AM Thu. September 4, 1997 2:04:27 PM Thu. September 4, 1997	Slot Fan Alert	serious serious	The speed of the I/O slot fan i	Please ch
baba baba	8	2:04:27 FM Thu. September 4, 1997	Power Supply Alert Power Supply Alert	serious	Power Supply identified by the Power Supply identified by the	Please ch
a baba Baba	9	2:05:17 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
a baba	3 10	2:05:18 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	11	2:06:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba baba	12	2:07:35 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	13	2:07:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	14	2:07:37 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	15	2:08:49 PM Thu, September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	16	2:09:28 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	17	3:01:10 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	18	3:01:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the	Please ch
baba	19	6:36:25 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	20	6:36:35 PM Thu. September 4, 1997	Slot Fan Aleit	serious	The speed of the I/O slot fan i	Please ch
baba	21	6:44:04 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	22	6:44:06 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
ag baba	23	6:44:55 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	24	6:44:57 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i	Please ch
baba	25	6:48:42 PM Thu, September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot (an i	Please ch







## ALERT MANAGER TABLE

SERVER 1 (NAME)

CPU ALERT DESCRIPTION: "CPU IDENTIFIED BY THE CPU NUMBER FAILED BECAUSE OF HIGH TEMPERATURE AND/OR LOW POWER"

NOTIFY YES/NO

SYSTEM BOARD FAN ALERT

NOTIFY YES/NO

TEMPERATURE SENSOR ALERT

NOTIFY YES/NO

POWER SUPPLY ALERT

NOTIFY YES/NO

ADAPTER ALERT

NOTIFY YES/NO

CANISTER ALERT

NOTIFY \_\_\_\_

SLOT FAN ALERT

NOTIFY \_\_\_\_\_

CANISTER FAN ALERT

NOTIFY \_\_\_\_

## SERVER 2 (NAME)

CPU ALERT

NOTIFY YES/NO

(TYPICAL METHODS)

CALL ALERT MANAGER DIALOG MODULE 216

CALL ALERT FLASH DIALOG MODULE 218

